# STRUCTURAL FLIGHT TEST OF AN AC-130A GUNSHIP EMPENNAGE

by


CAPTAIN JOHN J. RUSSELL



RESEARCH REPORT 71-9

GCTOBER 1871

NATIONAL TECHNICAL INFORMATION SERVICE Springfield, Va. 22151



UNITED STATES AIR FORCE ACADEMY

COLORADO 80840



Security CC ssification			
DOCUMENT CONT			
(Security classification of title, body of abstract and indexing  1. ORIGINATING ACTIVITY (Corporate author)	annotation must be a		rerall report is classified) URITY CLASSIFICATION
Dean of Faculty		1	SSIFIED
USAF Academy, Colorado 80840		26. GROUP	
boar academy, cororado cocaco		is. Theor	
3. REPORT TITLE		L	
STRUCTURAL FLIGHT TEST OF AN AC-130A GUNE	HTP EMPENNACI	7	
birdordana razont rabi of his no-tyon done	III. IAII DIVINIO	•	
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)			
Research Report			
5. AUTHOR(S) (First name, middle initial, lest name)			
Captain John J. Russell			
oup to the both of habitets			•
6. REPORT DATE	TA. TOTAL NO. O	FFAGES	75. NO. OF REFS
October 1971	64	1	0
SE. CONTRACT OR GRANT NO	90. ORIGINATOR"	REPORT NUMBE	
b. PROJECT NO.	RR 71-9		
c.	SO. OTHER REPO	RT NO(S) (Any oth	er numbers that may be sesigned
	this raport)		
d.	NONE		
10. DISTRIBUTION STATEMENT	_ <del></del>		
Distribution of this document is unlimite	ð		
	•		
11. SUPPLEMENTARY NOTES	12. SPONSORING	CILITARY ACTIV	ΤΥ
		_	
	Dean of Fa		. 000) 0
	USAF Acade	my, Colora	do 80840
3. ABSTRACT			
An AC-130A aircraft empennage was instr	umented with	electrical	-resistance strain
gages and flight test data was obtained f			
General Electric Vulcan cannon firings, a			
descriptions of the test instrumentation,		-	-
and results are contained in the report.			
empennage area based on minimum margins o			
Lockheed stress analysis. Results show t			
either 20mm or 40mm, are quite small and			
left hand orbit maneuver and the gun firi			
produced by antiaircraft evasive maneuver	s were siso	cound to be	well below design
limits.			
*			
DD , FORM 1473		UNC	LASSIFIED
		Co analas	Classification

## STRUCTURAL FLIGHT TEST OF AN AC-130A GUNSHIP EMPENNAGE

by

Captain John J. Russell

UNITED STATES AIR FORCE ACADEMY

RESEARCH REPORT 71-9

OCTOBER 1971

The research reported in this document was made possible in part by support extended to the faculty of the United States Air Force Academy by the Air Force Systems Command.

Additional copies of this document may be obtained by writing to the Director of Faculty Administration, United States Air Force Academy, Colorado 80840.

Editorial Review by Captain John B. McTasney
Department of English

This Research Report is presented as a competent treatment of the subject, worthy of publication. The United States Air Force Academy vouches for the quality of the research, without necessarily endorsing the opinions and conclusions of the authors.

# TABLE OF CONTENTS

	Pa	ge
	Abstract	v
	List of Figure:	vi
	List of Tables	ii
	List of Symbols	ix
I.	Introduction	1
	Improved Theoretical Stress Analysis	1
	New Actual Stress Analysis	1
II.	Instrumentation	3
	Strain Gages	3
	Temperature Compensation	4
	Bridge Balance Units	5
	Recorder	5
	Power Supply	5
III.	Aircraft Area Tested	5
	Strain Gage Location	7
	Vertical Stabilizer Gages	7
	Aft Fuselage Gages	9
	Gun Mount Gages	12
IV.	Flight Test	13
	Pre-flight	13
	In-flight	13
	Post-flight	13
V.	Results	14
	Calculations	14
	Level Flight Stresses	15
	Gun Firing Stresses	15
	Evasive Maneuver Stresses	15

VI.	Conclusions and Recommencations	•	•	•		•		•	•				16
VII.	List of References				•					•			Ņ
VIII.	Appendix											_	21

### ABSTRACT

An AC-130A aircraft empennage was instrumented with electrical-resistance strain gages and flight test data was obtained for anti-aircraft evasive maneuvers, 20mm General Electric Vulcan cannon firings, and 40mm Bofors gun firings. Complete descriptions of the test instrumentation, test conditions, strain gage locations, and results are contained in the report. Strain gages were located in the aircraft empennage area based on minimum margins of safety as found in the original Lockheed stress analysis. Results show that those stresses caused by gun firing, either 20mm or 40mm, are quite small and that the sum of the stresses due to the left hand orbit maneuver and the gun firing is well below design limits. Stresses produced by antiaircraft evasive maneuvers were also found to be well below design limits.

# LIST OF FIGURES

Figure	Pag	ţе
1	Overall Equipment Schematic	2
2	Wheatstone Bridge Schematic	ŀ
3	AC-130 Aircraft Station Diagram	5
4	Vertical Stabilizer Structure	3
5	Aft Fuselage Structure FS 737 to FS 869 10	)
6	Aft Fuselage Structure FS 869 to FS 1041	L
7	Number 4 - 40mm Gun	5
8	Vertical Stabilizer - Main Beam	5
9	Vertical Stabilizer - Auxiliary Beam	5
10	Vertical Stabilizer - Rear Beam	ł
11	Fuselage Station 814 Frame	5
12	Fuselage Station 847 Canted Bulkhead Installation 26	5
13	Fuselage Station 990 Frame	7
14	Upper BL 61 Longeron Fitting Fuselage Station 737 Fwd and Longeron	3
15	Lower B6 61 Longeron Fuselage Station 737 Aft 28	3
16	Upper BL 61 Longeron Fitting Fuselage Station 1041.5 29	)
17	Upper B6 61 Longeron Section at Fuselage Station 992 29	<b>)</b>
18	Upper B6 61 Longeron Section at Fuselage Station 1020 29	)
19	Lower B6 61 Longeron Fitting at Fuselage Station 1041.5 Fwd.30	)
20	Lower Bl 61 Longeron Section at Fuselage Station 1030 30	)
21	Upper Dorsal Longeron Fitting at Fuselage Station 946 31	Ĺ
22	Aft Fuselage Skins and Splices	2
23	Definition of Symbols in Tables III and IV	5
24	Typical Trace .40mm. Gages G1 and G2	į.
25	Typical Trace .40mm. Gage AF13	
26	Typical Trace .40mm. Rosette Gage VS4R	
27	Typical Trace .40mm. Gage VS6	5

28	Typical	Trace	.40mm.	Rosette	Gage	AF21R	•			•	•	•	•	36
29	Typical	Trace	.40mm.	Gage AF1	. 0							•		36
30	Typical	Trace	.20mm.	Rosette	Gage	AF21R	•				•			37
31	Typical	Trace	.20mm.	Gage AF1	.0				-		•			37
32	Typical	Traces	- Ant	iaircraft	Eva	ive Ma	ne	uve	TS					38

# LIST OF TABLES

Table			Page
1	Summary of Vertical Stabilizer Strain Gage Locations .		39
11	Summary of Aft Fuselage and Cun Strain Gage Locations		41
III	Experimental Stresses Vertical Stabilizer		43
IV	Experimental Stresses Aft Fuselage and Gun		45

## LIST OF SYMBOLS

- $\Delta \sigma_{LF}$  = Change in stress from installation stress to level flight stress.
- $\Delta\sigma_{o}$  = Change in stress from installation stress to left hand orbit stress.
- $\Delta\sigma_{+}$  = Change in stress from left hand orbit stress to positive peak of gun fire stress.
- $\Delta\sigma_{\perp}$  = Change in stress from left hand orbit stress to negative peak of gun fire stress.
- $\Delta\sigma_{\rm max}$  = Change in stress from installation stress to positive peak of gun fire stress or positive peak of entiaircraft evasive maneuver stress.
- $\Delta\sigma_{\min}$  = Change in stress from installation stress to negative peak of gun fire stress or negative peak of antiaircraft evasive maneuver stress.
- VS9 = Sample linear gage designation (Vertical Stabilizer 9).
- VS1OR = Sample resette gage designation (Vertical Stabilizer 10 Rosette).

NOTE: These stresses are normal stresses when associated with linear gages and shear stresses when associated with rosette gages.

## STRUCTURAL FLIGHT TEST OF AN AC-130A GUNSHIP EMPENNAGE

Several operations separate the AC-130A gunship from its transport counterpart, the C-130A. Although loads imposed by the assault landings on transport aircraft cause more severe landing stresses than those encountered in gunship operations, side firing weapons impose loads on the gunship similar to lateral gusts, but with a much higher frequency of occurrence. Evasive maneuvers to avoid antiaircraft fire also impose unusual loads on gunships directly related to the severity of the gunfire. Therefore, while both transport and gunship versions use the same airframe, their operational environments are quite different.

## Improved Theoretical Stress Analysis

Improvements in theoretical stress analysis techniques make the original stress analysis obsolete, although newer analysis techniques usually prove the older analysis to be conservative. Static tests have shown some of the assumptions in the original analysis to be incorrect, and appropriate modifications to the analysis were made. Therefore, while the tests show the theoretical analysis adequate for normal operations, they have not demonstrated the same adequacy for gunship operations.

# New Actual Stress Analysis

Since a new stress analysis was not conducted for the AC-130A, gunship configuration, an experimental flight test investigation of stresses imposed by gunfiring and antiaircraft evasive maneuvers was conducted, not only to determine possible trouble areas (or conversely to determine their nonexistence), but also to extend gunship technology in the area of structural requirements criteria. The test results would also yield guide lines for the selection of a larger weapons system for follow on programs.




FIG. 1 OVERALL EQUIPMENT SCHEMATIC

### INSTRUMENTATION

A complete schematic of the instrumentation package used in the test is shown in Figure 1 on the facing page. A standard Wheatstone bridge circuit, using a parallel bridge balance and a calibration resistor, was employed (See Figure 2). Automation Industries C12-121 were used for all linear gage applications, while C12-122D-R3Y were used for all rosette applications. A gage of the same type as the active gage was used as the temperature compensating gage in all cases.


Strain gages. Electrical resistance strain gages were selected as the transducers or the test because they possess the following advantages:

- 1. Direct strain indication at a selected point.
- 2. No need for theoretical calculations to obtain desired results; therefore, a direct comparison may be made between the measured strain and that predicted by the theoretical stress analysis.
- High reliability for short term tests without elaborate installation procedures.
- 4. Continuous dynamic output; therefore, yielding frequency as well as amplitude data.

Two types of gages were used in the test, linear, and delta rosette. Linear gages capable of measuring only uniaxial strain were employed wherever the direction of principal strain was known, as in members which are loaded axially or in bending. Delta rosettes, three linear gages arranged at 120 degree spacing, were used when the direction of principal strains were unknown, such as for semi-tension shear panels and fuselage skin. Eleven linear and five rosette gages were utilized on the vertical stabilizer. Fourteen linear and three rosette gages were used to study aft fuselage stresses. In addition, two linear gages were placed on the 40mm gun mount such that present test data could be correlated with the results of a test conducted at Fort Carson, Colorado in August, 1970. In that test a 40mm gun mount was fully instrumented

with strain gages to determine how gunfiring loads were transmitted by the mount to the aircraft.

Temperature compensation. The temperature compensating gage and two 120 ohm precision resistors used to complete the bridge were fixed to an aluminum or steel block, depending upon the parent material of the active gage (See Figure 2). The block was then located as close as possible to the active gage, using a non-strain transferring adhesive to bond the block to the aircraft. The dummy block was placed near the active gage to complete the bridge circuit at the active gage, therefore obtaining both temperature compensation and common mode rejection.



Common mode rejection is the ability of the circuit to eliminate noise which appears on pairs of input lines by means of cancellation. This is accomplished in this circuit by having equal length lines leading to the gage and returning from the bridge such that the same noise is picked up by each pair of the wires returning the signal to the amplifiers. Since a differential amplifier was used, signals common to both lines are eliminated, thus obtaining common mode rejection.

Bridge balance units. The balancing circuits and calibration resistor (See Figure 2) were contained in the bridge balance units (BBU). Four BBU's with 12 channel capability and one BBU with ten channel capability were used in the test system, allowing for 58 channels of data. The calibration resistor was chosen to obtain a simulated strain of -1869 microstrain. Therefore, when the calibration resistor was switched into the circuit, a signal was generated equivalent to the signal of an 1869 microstrain compression load.

Recorder. A Leach Model MTR 3240 recorder with 14 channel data capability was used to record all the strain data. Since the output of only one BBU could be recorded at anytime, only 12 channe's of the recorder were used. The data was recorded at a tape speed of 30 inches per second.

Power supply. Two power supplies were employed: one supplied 9.8 VDC to the strain gage network and the other supplied power to the amplifiers. Both were supplied by 115 VAC, 400 hertz aircraft power. Standard 28 VDC aircraft power was used for the tape recorder. The strain gage power supply exhibited a breakdown in the AC-DC conversion and started passing a 400 hertz ripple at a very low voltage causing some problems.

#### AIRCRAFT AREA TESTED

The empennage area of the aircraft was selected for the test because it was thought that most of the force resisting gun recoil would be provided by the vertical stabilizer. These forces could, therefore, produce a large gust type loading on the vertical stabilizer and a large torsional load on the aft fuselage. This area was also considered a potential trouble spot because all gunships fly with the rear cargo door open creating an open cross-section which is structurally inefficient for carrying torsional loads.




FIG. 3 AC-130 AIRCRAFT STATION DIAGRAM

The critical design conditions for the empennage were 1) asymmetrical power, 2) 15 psi fuselage pressurization, 3) maneuver loading, 4) lateral gust, and 5) hard rudder kick. While the lateral gust condition most closely simulates gunfiring loads, the dominant design condition for the empennage structure was the asymmetric condition.

The empennage, especially the vertical stabilizer, does not carry large dead weight loads. Hence, when the strain gages were installed, the empennage was in a zero stress condition. Even if this were not true, a great deal of information on over-stresses due to gunfiring and evasive maneuvers could be obtained, although the magnitude of the total stress could not be used. All stresses in this report will be referred to as changes in stress from the installation zero stress.

## Strain Gage Locations

Strain gages were placed at points in the aft fuselage and vertical stabilizer with minimum margins of safety, based on References 1 and 2 in the List of References. Figure 3, page 6, provides fuselage station (FS), water line (WL), buttock line (BL), and vertical stabilizer station (VSS) information to aid in the general location of each gage. Locations of sensors, 20mm guns, and 40mm guns in relation to the gages may also be obtained from Figure 3. All gages were located aft of FS 737.

Vertical stabilizer gages (VS). Only the main load carrying members of the vertical stabilizer were instrumented. Figure 4, page 8, illustrates the general structural configuration of the vertical stabilizer, the main load carrying members being the auxiliary beam, main beam, and rear beam. All of these members were designed as semitension field beams. No gages were employed on the vertical stabilizer leading edge. Figure 4 also aids in finding the general location of all vertical stabilizer gages. Figures 8, 9, and 10 (Appendix) show the exact location of each gage on the auxiliary, main, and rear beams.





FIG. 4 VERTICAL STABILIEER STRUCTURE


The structural members instrumented were beam caps (VS5), stiffeners (VS3, VS6, VS14, VS14A, VS17), shear webs (VS4R, VS7R, VS8R, VS13R, VS18R) and fittings (VS9, VS10, VS19, VS20). Some gages were used only as checks on loads to insure the loads were below design levels. The check gages are noted in Table I (Appendix), which is a summary of vertical stabilizer strain gage locations, with additional information as to the critical design condition for each part, type of stress, and margin of safety.

Aft fuselage gages (AF). Figures 5 and 6, following, illustrate the aft fuselage internal structure. As in the vertical stabilizer only primary structure was instrumented. The basic fuselage structure is essentially a single cell thin walled tube (the aircraft skin) supported by transverse frames or rings as well as symmetrically arranged longerons. The skin carries only a shear load, while the frames carry combined axial and bending loads. The C-130 utilizes only four longerons arranged symmetrically at upper and lower BL 61.625.

Frames instrumented were at FS814 (AF4, AF5)(See Figure 11), FS 847 (AF6)(See Figure 12), FS 990 (AF1, AF3)(See Figure 13.) The longerons at upper and lower BL 61.625 were extensively instrumented, with gages being located at splice fittings or at critical locations as shown in Figures 14, 15, 16, 17, 18, 19 and 20 (AF7, AF8, AF10, AF11, AF12, AF13, AF14, AF15)(See Appendix). Gage AF18 was located on the upper dorsal longeron fitting as shown in Figure 21 (Appendix). The dorsal fin provides the fuselage with a second structural cell to add extra strength where the fuselage corss-section is open (due to the cargo door being open.) Three resettes were placed on the fuselage skin (AF20R, AF21R, AF22R) as shown in Figure 22 (Appendix).

Table II (Appendix) provides summary information on all aft fuselage gages. Since the cargo ramp, aft cargo door, and horizontal stabilizer carry no unusual loads unique to gunship operations, they were not instrumented.





Gun mount gages (G). The two gages located on the 40mm gun mount are shown in Figure 7, below. Gage Gl measured the tipping load created by firing. This was accomplished by locating Gl on the elevation rod. Gage G2 was installed on the trunnion rod which is the primary member for transmitting the gun recoil into the mount.




Figure 7 Number 4 40mm Gun

### FLIGHT TEST

The flight test was conducted at Eglin AFB, Florida in September 1970 during simulated combat conditions in which other aircraft systems were being evaluated. The data vas taken during test flights on 23, 24 and 30 September. The aircraft test bed was AC-130A, S/N 56-0490. Tests were conducted firing both 20mm Vulcan cannons and firing each 40mm Bofors individually. The pilot conducting the test had combat experience in AC-130A aircraft and closely simulated actual combat evasive maneuvers used in avoiding antiaircraft fire.

<u>Pre-flight</u>. Before each flight the DC offset of each amplifier was zeroed and all bridges were balanced using the bridge balance units. A milliammeter was used to balance each bridge. A signal was then recorded with the bridge balance units shorted out of the system to obtain the zero level of the amplifiers. Signals from each BBU were then recorded at the zero level.

In-flight. With the aircraft in straight and level flight, signals were recorded from each BBU to obtain the level flight strains. Data was then recorded using each BBU in turn while each 40mm gun was fired. Both single shot and rapid fire, bursts of two or more rounds at two rounds per second, were recorded. All data on the 20mm guns is for both guns firing simultaneously at a rate of 2450 rounds per minute for approximately one second. In addition, five antiaircraft evasive maneuvers were conducted, each one being recorded on a different BBU.

Post-flight. The tapes were played back and the signals transferred to oscillograph paper using a Honeywell Model 7600 Data Recorder at Flight Dynamics Laboratory, Wright-Patterson AFB, Ohio. Two passes were made at the data, one using no filter and one using a low pass filter with a cut off frequency of 280 hertz. The data was filtered to eliminate the 400 hertz signal supplied to the strain gages by the degraded power supply.

#### RESULTS

A summary of the test results is presented in Table III for the vertical stabilizer and in Table IV for the aft fuselage. Values presented are (1) stress changes due to level flight loads,  $\Delta\sigma_{LF}$ , (2) stress changes due to the left hand orbit,  $\Delta\sigma_{o}$ , (3) positive and negative over stresses produced by gun firing,  $\Delta\sigma_{+}$  and  $\Delta\sigma_{-}$ . The positive and negative overstresses are then added (vectorially in the case of shear) to the mean stress level,  $\Delta\sigma_{o}$ , to yield the maximum and minimum stress changes,  $\Delta\sigma_{max}$  and  $\Delta\sigma_{min}$ . The symbols are defined in Figure 23 (Appendix) for gun firings and for antiaircraft maneuvers.

Calculations. For all linear gages the stresses appearing in Lible III and IV are normal stresses and in this case the maximum stress change,  $\Delta o_{max}$ , is just the algebraic sum of the left hand orbit stress,  $\Delta\sigma_{o}$ , and the positive stress change due to gun firing,  $\Delta\sigma_{+}$ . But in the case of shear stresses, the strains had to be obtained from both the orbit traces and the gunfire traces. The differences between these two traces were not necessarily the same for all three gages in the rosette; therefore, the shear stresses for the left hand orbit maneuver and gun firing were obtained respectively from the left hand orbit strains and positive and negative gunfire strains separately. Then the sum of the strains due to both were added to yield the shear stress due to both the orbit and gun firing, using the standard equation for converting rosette strains to shear stresses. Hence, the sum of the shear stress due to the orbit and the shear stress due to gunfire does not equal the maximum shear stress. When reading Tables III and IV, care should be used in interpreting data from rosette gages, those using an R in their designation, for example VS18R. All stresses from rosette gages are in terms of shear stresses, since the design of all fuselage skin and beam webs was based on shear stress.

Level flight stresses. The stresses in Tables III and IV are presented in terms of changes in stress from the stress existing when the gages were installed. Observation of the level flight change in stress,  $\triangle_{LF}$ , reveals that in the majority of cases stress levels remained constant from the installation condition to the level flight condition. Since positive loads are encountered on the horizontal stabilizer in flight and negative loads due to the dead weight are encountered in the installation condition, it is safe to conclude that the gages were installed at nearly a zero stress state.

Gun firing stresses. Sample traces are shown in Figures 24, 25, 26, 27, 28 and 29 for 40mm gun firings, in Figures 30 and 31 for 20mm gun firings and in Figure 32 for antiaircraft evasive maneuvers.

The highest normal stress recorded on the vertical stabilizer was 5128 psi compression on gage VS20 which is located on the rear beam fitting at VSS 0. This stress was produced when both 20mm guns were fired simultaneously. The highest shear stress recorded in the vertical stabilizer was 880 psi on gage VS4R, which was located on the rear beam shear web next to the lightening hold at VSS 10.88. This stress was recorded during the firing of Number 3 40mm gun.

Strains recorded on the two gages located on the 40mm gun were higher than those recorded during tests on the gun mount at Fort Carson, Colorado during August 1970. The probable cause of this was the more flexible platform, a sheet metal bed of a 2-1/2 ton truck used at Fort Carson. Subsequently more recoil was expended in truck deformation than occurs on the aircraft because of the more rigid mounting in the aircraft.

Evasive maneuver stresses. During an antiaircraft evasive maneuver a high normal stress in the aft fuselage of 3258 psi compression was recorded on gage AF6 which is located at the canted bulkhead at FS 847.

#### CONCLUSIONS AND RECOMMENDATIONS

The most obvious conclusion that can be made from a study of the data in Tables III and IV is that none of the loading mechanisms in question (i.e., 40mm gunfiring, 20mm gunfiring, or antiaircraft evasive maneuvers) impose loads on the aircraft approaching maximum design loads. All stresses measured were less than 10% of the design maximum stresses; they, therefore, present no foreseeable fatigue problems. In many cases the measured stresses were in the noise level of the recording system and are shown only for relative purposes.

Since the stress levels are quite low, it is difficult to form any definite conclusions as to the relative severity of stresses produced by 40mm gunfire versus 20mm gunfire. Overall results indicate that firing the 20mm guns simultaneously produced higher stresses on the majority of instrumented structure than did the 40mm gunfiring. This is understandable in that the 20mm guns have a much larger moment arm, from the aircraft center of gravity, than do the 40mm guns. Also when both 20mm guns are fired simultaneously, they produce roughly the equivalent recoil of one 40mm gun. Therefore, larger loads are produced in the vertical stabilizer to resist the moment produced by the 20mm gun firing than are produced when a single 40mm gun is fired. Although the 40mm guns are never fired simultaneously, both 20mm guns are fired simultaneously in the first burst, but subsequently are usually fired independently.

Since 40mm gunfiring introduces such small loads in the vertical stabilizer and aft fuselage, most of the recoil force is being expended in producing aircraft translational motion along the radius of the orbit (the aircraft is simply being pushed outward very slightly). Very little energy appears to be going into structural deformation. While the outward motion does not present a problem with the 40mm gun; it could present a more serious problem with a larger gun.

Multiple firings caused no amplification of stresses. The stresses measured for single firings were exactly the same as close measured for multiple firings (4-6 rounds fired at a rate of 2 rounds per second). It had been feared that the gunfiring grequency was quite near some of the fuselage's natural frequencies and might cause some dynamic magnification of stresses. This suspicion was found to be false.

If a larger gun is to be installed on an AC-130, the following instrumentation should be included, based on the results of the present test. Strain gages should be mainly concentrated in the immediate vicinity of the gun tiedown structure. A few gages should also be placed in the same positions as those in the report for comparison purposes.

## LIST OF REFERENCES

- 1. Aft Fuselage Stress Analysis, Model C-130A. Lockheed Report No. ER 754M July 23, 1954.
- 2. Vertical Stabilizer Stress Analysis, Model C-130A. Lockheed Report No. ER 765M Jan 23, 1955.
- Dally, J. W., and William F. Riley. <u>Experimental Stress Analysis</u> McGraw-Hill Book Company, Inc., New York, 1965.
- 4. Dave, Richard C., and Adams, P. H. Experimental Stress Analysis and Motion Measurement. 2nd Edition, Columbus, Ohio, Charles E. Merril Books, Inc., 1964.
- 5. AF Technical Order 1C-130A-3, Structural Repair.

APPENDIX

Preceding page blank




FIG. B VERTICAL STABILITER - MA & BRAM.






FIG 9. VERTICAL STABLISHER - AUXILLARY BRAN.
Preceding page blank 23





NOTE: WAR, VS19, AUD VS10 ON FRONT OF BEAM

FIG 10 VESTICAL STABILIZES REAR BEAM VIEW LOOKING FORWARD





FIG ! FS & FRANE







FIG 12 SOUTH BULLIAND HUTALLATION FI SAT



AFI
SECTION AA

FIG 13 FS 990 FRAME




FIG IA UPPER BLGI LONGERON FITTING RT 1977


AFIO ATION ATION THE SIDE VIEW

SIDE VIEW

SECTION A.A. LONGERON ONIX

FIG 15 LOWER BLGL LONGERON FY IN AFT

TOP VIEW



16 UPPER BLGI LONGERON FITTING FS 1041.5




FIG 17 UPPER BLG LONGERON
SECTION AT FS 992




FIG IR UPPER BLGI WHORPON




FIG 19 LOWER BLGI LONGERON FITTING FS 1041 FIND







FIG. 20 Lower BL 61 Longeron Section At FS 1030






TECTION AA

FIG 2) UPPER DOSSAL LONGERON FITTING FS 946





DEFINITION OF SYMBOLS FOR GUN FIRING STREETS




FIG 23 PEFINITION OF SYMBOLS IN TABLES III AND III




FIG 24 TYPICAL TRACE 40 Mm GAGES GI AND G2




FIG. 25 TYPICAL TRACE . 40mm . GADE AFIS




FIG 26 TYPICAL TRACE - 40mm - ROSETTE GAGE VEAR




FIG 27 TYPICAL TRACE - SOMM - SASE VSG




FIG. 28 TYPICAL TRACE . 40 mm . ROSETTE GAGE AFZIE




FIG. 29 TYPICAL TRACE . 40 MM . GAGE AFIO




FIG. 30 TYPICAL TRACE : 20mm : ROSETTE CAGE AFZIR




FIG 31 TYPICAL TRACE - 20 mm GAGE AFTO




FIG 32 TYPICAL TRACES MITIARCRAFT GRACIVE HANGUVERS

DESIGN MODE OF FAILURE	Forced Crippling (B-48)	Used Only As A Check On Shear Flow (B.50)3	Grippling (B-49)	Forced Crippling (B-45)	Web to Cap Attachment Bearing $(B-\mu 6)$	Web Attachment. Shear on DD6 Rivets, Br $\frac{3}{3}$ $\frac{5}{16}$ " ST'L L'KB (8-45)	Attachment Main Beam Cap To Fitting. 1/4" Lock Bolts AWD	NAS 336 . 3/8" Boits in Shear and Bearing (B-70)	Used Only As Check On Shear Flow (g=185 15/in) (B-35)	End Connection - 2-1/4" St'l LKB & 2-DD6 Rivets - BRG (B-36)
MINIMUM MARGIN OF SAFETY	0.08	ı	0.17	0.00	0.51	0.10		0.20	á	0.23
CRITICAL DESIGN CONDITION	A.P.C.	Zero <sup>2</sup> Yaw	A.P.C.	A.P.C.	A.P.C.	A.P.C.	A.P.C.	A. P. C.	A.P.C.	A.2.0.
PART MAT'L.	7075- <b>1</b> 6 <b>Extr</b> .	7075-T6 Clad	70, 5-16 Extr.	2024-14 Extr.	7075-T6 Clad	7075-T6 Clad	2014-T6 Forg	2014-T6 For	2024-T4 Clad	7075- <b>16</b> Extr.
P. NO.	351741	1	351691	35172	351690- 11	351690- 3	344101	344101	351é82- 6	351682- 14
LOCATION	Main Beam . Stiffener . VSS 45	Rear Beam . Shear Web . Next to Lightening Hole VSS $44$	Main Beam . Cap . VSS 44	Main Beam . Stiffener . VSS 29	Main Beam . Shear Web Panel at VSS 25	Main Beam . Shear Web Panel at VSS 16	Main Beam . Fitting . VSS O B.L. 16.90	Main Beam . Fitting . VSS 0 B.L 16.90	Auxillary Beam Shear Web Above VS 10 Stiffener	Auxillary Beam. Stiffener. VSS 10
FIGURE REF.	W	5	W	N	M	80	K	М	<del>1</del>	4
GAGE	VS3	VS4R	VS5	<b>v</b> s6	VS7R	ags <sub>A</sub> 39	VS9	vslo	VS13R	$\mathbf{vs1}^{\mathrm{h}}$

Table I, Page 1 SUMMARY OF VERTICAL STABILIZER STRAIN GAGE LOCATIONS

F DESIGN MODE OF FAILURE	End Connection - 2-1/4" ST'L LKB 2-DD6 Rivets - RRG (R-36)	Used Only As A Check On Axial Load Since Critical Stiffener at	Used Only As A Check On Shear Flow Since Critical Panel at VSS 127 - VSS 142 was Inacces- sible.	Bending (B-71)	Bending (B-61)	Crippling (8-55)
MINIMIM MARGIN OF SAFETY	0,23	ı	1	0.01	0.01	0.27
CRITICAL DESIGN CONDITION	A.P.C.	Zero Yaw	Zero Yaw	A.P.C.	A.P.C.	A.P.C.
PART NO. MAT'L.	351682- 7075-T6 14 Extr.	7075- <b>T</b> 6 <b>Extr</b> .	7075- <b>T</b> © Clad	8650 <b>ST'L</b>	8630 <b>ST'</b> L	7075-T6 Extr.
NO.	351682- 14	ı	1	352030	352030	351703
LOCATION	Duplicate of VS14	Rear Beam - Stiffener VSS 111	Rear Beam - Shear Web Panel Between VSS 92 and VSS 111	Rear Beam - Fitting - VSS O	Rear Beam - Fitting - VSS O	Rear Beam - Cap at VSS 100
FIGURE REF.	ন	ľ	ľV	<u>ار</u>	77	۲,
CACF	VS14A	VS17	vs18R	VS19	VS20	VS21
					40	

Table I, Page 2

Asymmetric Power Condition
 Instantaneous Rudder
 Refers to Theoretical Stress Analysis See Ref. 1.

DESIGN MODE OF FAILURE	Tension (A-82) <sup>2</sup>	Compression (A-85)	Compression (264)	Compression (264)	Tension (269)	Tens. + Bending (188)	Tens. + Bending (189)	Comp. + Bending (169)	Compression (195)	Compression (193)	Tens. + Bending $(194)$
MINIMUM MARGIN OF SAFETY	0.01	0.20	0.01	0.18	0.08	0.07	00.0	90.0	0.03	0.17	0.12
CRITICAL DESIGN CONDITION	A.P.C.	A.P.C.	A.P.C.	15 psi	Cargo Log.	MANV.	MANV.	LAT. GUST	LAT.GUST	LAT. GUST	LAT. GUST
PART MAT¹L.	7075-T6 Extr.	7075- <b>T</b> 6 <b>Extr.</b>	7075- <b>T6</b> <b>Extr.</b>	7075-T6 Extr.	7075-16 <b>Extr</b> .	7075- <b>1</b> 6 <b>Extr.</b>	7075- <b>1</b> 6 <b>Extr</b> .	7075-16 <b>Forg</b>	7075- <b>T</b> 6 <b>Ex</b> tr.	7075-T6 Extr.	7075-T6 Forg
LOCATION NO.	FS 990 Frame. Bottom, Section A-A	FS 990 Frame. Middle. Section B-B	FS 814 Frame. Outside. Section A-A	FS 814 Frame. Top. Section B-b	FS $847$ . Canted Blk Hd. Section A-A	Upper BL 61 Fitting FS 735 FWD.	Upper BL 61 Longeron FS 729 Section 337929 Through Bolt 1	Lower BL 61 Fitting FS 744 AFT Section C-C	Upper BL 61 Longeron FS 992	Upper BL 61 Longeron FS 1020	Upper BL 61 Fitting FS 1039 Sec B-B 537595
FIGURE REF.	9	Q	<b>!</b> -	<b>-</b>	ω	6	10	11	12	13	14
GAGE	AF1	AF3	AF4	<b>AF</b> 5	AF6	AFŢ	<b>%</b> ¥ <b>V</b> 41	AF10	AF11	AF12	AF13

Table II, Page 1 SUMMARY OF AFT FUSELAGE AND GUN STRAIN GAGE LOCATIONS

	CAGE	REF.	LOCATION	PART NO. MAT'L	CRITICAL DESIGN L CONDITION	MINIMIM MARGIN OF SAFETY	DESIGN MODE OF FAILURE
	AF14	15	Lower BL 61 Fitting FS 1034 Sec A-A 337426	126 7075-T6 Forg	-T6 LAT.GUST	0.04	Comp. + Bending (176)
	<b>AF</b> 15	16	Lower BL 61 Longeron FS 1050	7075-16 Extr.	-T6 LAT.GUST	8.0	Comp. + Bending (176)
	<b>AF</b> 18	17	Fitting Upper Dorsal Longeron FS 946 Section C-C	7075-T6 For g	-T6 MANV.	0.02	Tens + Bending (133)
	AFZOR	18	Fuselage Skin FS 741 Upper BL 79 Panel Q	7075-T6	-T6 A.P.C.	0.05	Shear (A-75)
	AF21R	18	Fuselage Skin FS 833 Lower BL 54 Panel K	7075- <b>T</b> 6 <b>CLAD</b>	-T6 A.P.C.	0.07	Shear (A-71)
	AF22R	18	Fuselage Skin FS 1000 Upper BL 32 Panel C	7075-T6 <b>CLAD</b>	-T6 A.P.C.	0.48	Shear (A-64)
42							
	Gl	19	40mm Gun. Elevation Rod	Steel	1 Recoil	Large	Compression
	છ	19	40mm Gun. Trunnion Rod	Steel	1 Recoil	Large	Tension

MINIMIM

CRITICAL

Table II, Page 2

Asymmetric Power Condicion Refers to Theoretical Stress Analysis, See Ref 2.

ن ن ن

i	i								
∆√min	474- 0	676 617 629	-642 -892= -750	-183 -550 183	239 224 192	183 102 138	-609 -677 -338	-798 -598 -399	442 176 -88
Δσ Δσ max	169 507 0	839 600 727	71 143 250	550 3678 550	210 253 327	316 227 77	338 677 846	678 399 997	363 645 45
۵۵.	948- 424-	236 109 -	-357	-550 -734 -	262 86	181 229 -	-609 -	-798 -598	219
۵۵+	169 507 -	347 132	357 428 -	367 183	158 119 -	100 50	338 677	673 399 -	50 201
CONDITION	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	4 Omm 2 Omm AAA	hOmm 20mm AAA
$ abla_{0}^{0}$	0	727	-285	183	190	277	0	0	594
∆o <sub>l.F</sub> *	0	319	0	0	0	0	0	0	152
LOCATION	Main Beam Stiffener at VSS 45	Rear Beam Shear Web Next to Lightening Hole at VSS $10.88$	Main Beam Cap at VSS 44	Main Beam Stiffener at VSS 29	Main Beam Shear Web Panel at VSS 25	Main Beam Shear Web Panel at VSS 16	Main Beam Fitting at VSS O, BL +16.9	Main Beam Fitting at VSS O, BL -16.9	Auxillary Beam Shear Web Above VSS 10 Stiffener
FIGURE REF.	и	<b>~</b>	W	<b>~</b>		K)	M	M	4
GAGE	VSZ	VS4R	VS5	<b>vs</b> 6	NS. 43	VSBR	6S <b>v</b>	vs10	VS13R

Table III, Page 1 EXPERIMENTAL STRESS VERTICAL STABILIZER

^omin	-37 -367 367	-370 -592 0	680 382 0	-1450 -2900 -483	-3760 -5128 -3408	-181 -978 -724
Δσ max	660 660 367	518 444 74	544 698 58	485 1257 483	-1937 -1709 -2848	181 454 362
_ کم	-403 -734	999- 1747-	109	-967 -2416 -	-911 -2279 -	-181 -978 -
۵۵+	293 293	444 370	155 165	967	911 1140 -	181 434 -
LOCATION	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	40mm 20mm AAA	կՕ <del>ռա</del> 20 <b>տո</b> <b>AAA</b>
δ <sub>0</sub>	367	47	541	-483	-2848	0
$^{ riangle G_{\mathbf{LF}}}*$	0	0	159	0	0	0
LCCATION	Auxillary Beam Stiffener at VSS 10	Rear Beam Stiffener at VSS 111	Rear Beam Shear Web Panel Between VSS 92 and 75S 111	Rear Beam Fitting at VSS O	Rear Beam Fitting at VSS O	Rear Beam Cap at VSS 100
FIGURE REF.	**	<b>~</b>	Ŋ	<u>ι</u>	<i>ا</i> ر	₹
GAGE	VS14	VS17	VS18R	vs19	<b>VS</b> 20	VS21

Table III, Page 2

	u.								
Δσ <sub>min</sub>	-226 -868 183	-440 -1100 -1100	-169 -304 338	1675 1516 1396	-1195 -1267 -3258	943 642 -3962	-428 -428 -71	267 -114 -2019	-481 -481 0
∆o <sub>max</sub>	6;9 868 377	183 183 366	677 846 338	2194 2393 1994	-724 -543 -905	1547 1698 1321	214 107 428	1029 1029 648	555 148 74
۵۵_	-415 -1057 -	-256 -917 -	-507 -643 -	-319 -479 -	-290 -362 -	-377	-357	-381 -762 -	-555
۵۵+	491 679 -	367 367	338 507 -	199 399	181 362 -	226 377	285 178 -	381 381	481 74.
CONDITION	<sup>1</sup> 4 Omm 2 Omm AAA	40mm 20mm AAA	<sup>1</sup> 4Omm 2Omm AAA	40mm 20mm AAA	40mm 20mm AAA	HOmm EOmm AAA	40mm 20mm AAA	40mm 20mm AAA	4 Ouran 2 Oran AAA
ο <sub>ο</sub>	188	-183	358	1994	-905	1321	-71	648	47
∆o <b>lf</b> *	0	0	0	0	0	0	0	ာ	47
LOCATION	FS 990 Frame Bottom at Section A-A	FS 990 Frame Middle at Section B-B	FS 814 Frame Outside at Section A-A	FS $814$ Frame Top at Section B-b	FS $847$ Canted Bulkhead Section A-A	Upper BL 61 Fitting at FS 735 Fwd	Upper BL 61 Longeron FS 729 Section Through Bolt 1	Lower Bi 61 Fitting FS 744 Aft Section C-C	Upper BL 61 Longeron FS 992
FIGURE REF.	9	9	٢	<b>6</b> -	ω	6	2	11	12
GAGE	AF1	A F?	<b>₽</b> ₽!↓	4 F S	<b>AF</b> 6	AF7	A F B	<b>AF</b> 10	<b>AF</b> 11

Table IV, Page 1
EXPERIMENTAL STRESSES AFT FUSELAGE

$\Delta\sigma_{ t min}$	-513 -550 37	-381 -572 -686	-1276 -1350 -912	257 257 -110	-257 -1247 37	571 503 465	602 296 1460	2122 2369 110	-3697
Δσ	770 403 37	1334 457 76	-547 -547 182	1100 1100 807	403 587 37	759 901 168	1049 1081 89	2346 1521 78	6160
707	-55c -587	-457 -648 -	-365 -438 -	-550 -550 -	-293 -1284 -	107	242 643 -	520 292 -	-3697
+ DQ +	753	1257 381 -	365 365	293	367 550 -	98 242 -	237 307	184 55	6160
CONDITION	l,Oman 2Oman AAA	40mm 20mm AAA	\cdot\cdot\cdot\cdot\cdot\cdot\cdot\cdot	l∤Omm 2Omm AAA	եմատ 20 <b>ատ</b> AAA	LOmm 20mm AAA	14 Oman 2 Oman AAA	ltOmm 20mm AAA	40mm 20mm AAA
ο <sub>ο</sub>	37	76	-912	807	37	029	792	2163	•
∆o <sub>lf</sub> *	0	0	0	0	0	0	0	0	ı
LOCATION	Upper BL 61 Longeron FS 1020	Upper BL 61 Fitting FS 1039 Section B-B	Lower BL 61 Fitting FS 1034 Section A-A	Lower BL 61 Longeron FS 1030	Fitting Upper Dorsal Longeron FS 946 Section C-C	Fuselage Skin . FS 741 . Lower BL 79 . Panel Q	Puselage Skin . FS 833 Lower BL >≒ Panel K	Fuselage Skin FS 1000 Upper BL 32 Panel C	40mm Gun Elevation Rod
FIGURE REF.	13	14	15	16	17	18	18	18	19
CACE	AF12	AF13	<b>AF</b> 1½	<b>AF</b> 15	<b>AF</b> 18	AFZOR	A P2 1R	A F22R	CI
- "									

Table IV, Page 2

$^{\Delta\sigma}_{\tt min}$	-2115
∆о max	1269
_ ۵۵	1269 -2115 1269
۵۵ +	1269
CONDITION $\Delta\sigma_{+}$ $\Delta\sigma_{-}$	4-Omm 2-Omm AAA
$\Delta\sigma_{\mathbf{o}}$	ŧ
^ LF*	ı
LOCATION	40mm Gun Trunnion Rod
FIGURE GAGE REF.	G: 1.9 4.Cmm